




RHOMAR WATER
Heat Transfer Fluids • Hydronic System Solutions

Boiler Fuel Efficiency Loss (%) as a Result of Scale Thickness (inches) in Boiler Tubes



2103 E Rockhurst St, Springfield, MO 65802
ph: 417-862-2600 • 1-800-543-5975 • fax: 417-862-6410

www.RhomarWater.com